

Aircraft Specification

1977 Piper PA-31-325 Navajo C/R

Airframe Hours: 4915:45 @ 03/Nov/2023

Engine Hours: Engine 1: 130:45 SOH Engine last overhauled 2011

Engine 2: 33:45 SOH Engine last overhauled 2017

Propeller Hours: Prop 1: Fresh prop/hub overhaul carried out Summer 2023

Prop 2: Fresh prop/hub overhaul carried out Summer 2023

Based in Iceland with Iceland issued CofA Fresh Annual Inspection and ARC underway







Avionics: Make and Model If On Board:

 COM 1
 GARMIN
 GNS 430

 COM 2
 GARMIN
 GNS 430

 ADF
 KING
 KR 87

NAV 1 GARMIN GNS 430 w/VOR/LOC/GS NAV 2 GARMIN GNS 430 w/VOR/LOC/GS

ILS DUAL HSI plus a No2 VOR/LOC/GS Indicator

DME KING KN 62A

TRANSPONDER w/MODE S GARMIN GTX 330 [a fresh check is required]

GPS GARMIN GNS 430
AUTOPILOT ALTIMATIC IIIC

CO-PILOTS PANEL
ENGINE MONITOR
AUDIO PANEL
GARMIN
GMA 340

ELT KANNAD 406









Aircraft Specification

AIRORALLO

OTHER INFORMATION:

The 325 variant of the Navajo is an 8-seater (2 crew & 6 pax)

2x 325HP Lycoming C/R TIO-540-F2BD

TBO 1800 Hours/12 Years

Engines last overhauled #1: in 2011 #2: in 2017

Engine Serial Numbers: #1: RL-4372-61A & #2: L-1555-68A

Hartzell HC-E3YR-2A 3-blade propellers - overhauled Summer 2023

Propeller serial numbers: DJ10283A & DJ 10292A

Propeller TBO is 2400 Hours or 72 months

Cargo door

Increased gross weight as it has VGs

Full P2 panel

P1 panel mounted chronometer

Deicing - see note further below

187USG fuel

KNOWN HISTORY:

The aircraft is the personal steed of the former owner of an Iceland based charter operation who has owned the aircraft for many years. The aircraft last flew several years ago but is being brought back into service right now

FURTHER NOTES:

- 1. Oxygen bottle and system removed to lighten the aircraft for better payload
- 2. Heated stall warning probe.
- 3. Aircraft is IFR certified in Iceland
- 4. Heated windshield status will be check before the Annual is completed
- 5. Airconditioning system was removed to lighten the aircraft for better payload

A WORD ABOUT THE DEICING:

The aircraft is deiced. All Boots in working order; three patches on right hand wing boot.

Left wing boot approx 130 hrs since installed.

Elevator: RH 130 Hrs. LH good working two patches. Fin boot in good condition no patches.

(LH Windshield electrical heated needs to be tested to check its working condition, so condition not known for now)

A WORD ABOUT THE ENGINES:

Low time since last overhaul. Engine data management system installed in 2015. Fitted with intercoolers

A WORD ABOUT THE PROPELLERS:

Both propellers and hubs were overhauled Summer 2023 at Brinkley Propeller Services in England

A WORD ABOUT THE AVIONICS:

The avionics were upgraded in 2015. Engine data management system installed in 2015

INTERIOR DETAILS:

Six forward facing rear cabin seats in Blue

EXTERIOR DETAILS:

Overall Whisper Grey with Blue and Medium Grey stripes Full strip, alodined, primed and resprayed in 1989 in USA





PRICING:

The guide price is USD\$229,000

VAT Note: Import VAT will be applicable for UK & EU





